

**SERVICEABLE VEHICLES AT THE PRESIDENCY**

<b>SRL</b>	<b>VEH NO</b>	<b>MAKE OF VEH</b>	<b>CHASSIS NO</b>
<b>(a)</b>	<b>(b)</b>	<b>(c)</b>	<b>(d)</b>
1	GM 7653 -13	TOYOTA LAND CRUISER V8	JTMHV09J2D4105119
2	VR 3125 - 14	TOYOTA LAND CRUISER V8	JTMHV09J7D4108615
3	VR 6105 - 16	TOYOTA LAND CRUISER V8	JTMHV09J1F503306
4	BA 2631 -13	TOYOTA LAND CRUISER V8	JTMHV09J6E4126010
5	ER 1593 - 15	TOYOTA LAND CRUISER V8	JTMHV09J4F4159234
6	GM 7471 - 13	TOYOTA AVALON	4T1BK1EB9DU011804
7	GW 2671 - 15	BENZ	WDD2120361B083433
8	GR 5170 - 15	BENZ	WDD2120361B085657
9	VR 4321 - 15	TOYOTA LAND CRUISER V8	JTMHV05T404169484
10	VR 2472 - 15	TOYOTA LAND CRUISER V8	JTMHV09J6D4114678
11	VR 3789 - 15	TOYOTA PRADO	JTEBH9FJ6F5090459
12	GN 8810 - 13	TOYOTA PRADO	JTEBXFJ0DK120473
13	VR 3789 - 15	TOYOTA PRADO	JTEBH9FJ6F5090459
14	GE 4161 - 14	NISSAN PATROL	JN8AY2NY0E9070919
15	GB 263 - 12	TOYOTA LAND CRUISER V8	JTMHV09J1C4078154
16	GE 2984 - 13	TOYOTA LAND CRUISER V8	JTMHV09J2D4091321
17	VR 4895 - 15	TOYOTA LAND CRUISER	JTMHV09JXC4083059
18	BA 2541 -14	TOYOTA LAND CRUISER	JTMHV09J8A5006049
19	GE 2944 - 14	TOYOTA LAND CRUISER	JTMHV05J204040028
20	AW 4738 - 13	TOYOTA LAND CRUISER V8	JTMHV09J8C4081200
21	NR 1105 - 16	IVECO	ZCFK050A705076471
22	VR 6472 - 16	TOYOTA LAND CRUISER V8	JTMHV09J3F5032775
23	CR 2048 - 15	TOYOTA LAND CRUISER	JTMHV09J2D4110837
24	ER 4416 - 10	TOYOTA LAND CRUISER	JTMHV09J9B4108535
25	WR 1658 - 10	TOYOTA LX	JTGE73J1A9002448
26	GB 6408 - 12	TOYOTA PRADO	JTEBX9FJXCK080338
27	ER 2132 - 14	TOYOTA LAND CRUISER V8	JTMHV09J2F4160771
28	ER 1607 - 15	TOYOTA LAND CRUISER V8	JTMHVX05J1B4023186
29	ER 2147 - 14	TOYOTA LAND CRUISER V8	JTMHV09J4E4125650
30	GT 3275 - 15	BENZ SALOON	WDD2120361B082894
31	GT 3230 - 15	BENZ SALOON	WDD2120361B084054
32	GS 681 - 13	TOYOTA LAND CRUISER V8	JTMHV09J2DH107629
33	VR 4012 - 15	TOYOTA PRADO	JTEBH9FJXFK158053
34	VR 3456 - 15	TOYOTA PRADO	JTEBH9FJ0F5091140
35	NR 1347 - 15	TOYOTA PRADO	JTEBH9FJ3F5092377
36	WR 3517 - 14	TOYOTA PRADO	JTEBH9FJ8F5096540
37	ER 4420 - 10	TOYOTA PRADO	JTEBH94FK149137
38	NR 4020 - 15	TOYOTA LAND CRUISER	JTMHV09J1E4123905
39	GE 2329 -16	TOYOTA LAND CRUISER V8	JTMHV05J804153885
40	VR 3567 - 15	TOYOTA PRADO	JTEBH9FJ8FK157838
41	GE 4162 - 14	NISSAN PATROL	JN8AY2NY1E9070802
42	WR 2914 - 15	TOYOTA LAND CRUISER	JTMHV09J4F5033160
43		TOYOTA PRADO	JTEBH9FJ7FK155224
44	WR 2921 - 15	TOYOTA PRADO	JTEBH9FJ7FK154980
45	VR 3123 - 15	TOYOTA PRADO	JTEBH9FJ8F5090236
46	VR 2838 - 15	TOYOTA PRADO	JTEBH9F0FK155016
47	GV 79 - 15	TOYOTA PRADO	JTEBH9FJ3FK162154
48	GS 7611 - 10	TOYOTA LX	JTGE73J1E9012841
49	GV 158 - 15	TOYOTA PRADO	JTEBH9FJ0FK170146
50	ER 1576 - 15	TOYOTA PRADO	JTEBH9FJ9FK161932
51	WR 2807 - 15	TOYOTA PRADO	JTEBH9FJ3FK163479
52	NR 1405 - 15	TOYOTA PRADO	JTEBH9FJ3F5092296
53	GV 139 - 15	TOYOTA PRADO	JTEBH9FJ7FK169947
54	NR 1483 - 15	TOYOTA LAND CRUISER V8	JTMHV09J6C4076092
55	VR 2012 - 15	TOYOTA LAND CRUISER V8	JTMHV09JXE4124194
56	GR 1453 - 16	TOYOTA LAND CRUISER V8	JTMHV09J9E4122968
57	GV 530 - 15/ ER 317 - 09	TOYOTA LAND CRUISER V8	JTMHV09J3E4124554

OFFICER HANDING OVER: HARISSON KOFI AWUKU

OFFICER TAKING OVER: CAPT SAMUEL ANANE-TANOR

58	UE 517 - 15	TOYOTA LAND CRUISER V8	JTMHV09J8E4122296
59	WR 2816 - 15	TOYOTA LAND CRUISER V8	JTMHX05J2E4061253
60	GN 7085 - 16	TOYOTA LAND CRUISER V8	JTMHX05J9E4061136
61	NR 1123 - 16	TOYOTA LAND CRUISER V8	JTMHV09J904121902
62	BA 5509 - 15	TOYOTA PRADO	JTEBU9FJ3FK083367
63	UW 318 - 14	TOYOTA PRADO	JTEBH9FJ3FK149422
64	GW 7621 - 13	TOYOTA PRADO	JTEBH9FJXDK100716
65	ER 1520 - 15	TOYOTA PRADO	JTEBH9FJ2FK158046
66	GN 7621 - 13	TOYOTA PRADO	JTEBH9FXDK100716
67	ER 1520 - 15	TOYOTA PRADO	JTEBH9FJ2FK158046
68	NR 1028 - 15	TOYOTA LAND CRUISER	JTMHV09J9E4121187
69	GE 2380 - 16	TOYOTA LAND CRUISER	JTMHV09J6D4095114
70	VR 5362 - 15	TOYOTA LAND CRUISER	JTMHV09J60476108
71	GV 115 - 15	BENZ AMBULANCE	WDB9066331P123572
72	GV 116 - 15	BENZ AMBULANCE	WDB9066331P116501
73	WR 1324 - 11	TOYOTA LAND CRUISER V6 AMBU	JTMDU09J5A5033470
74	WR 2813 - 15	TOYOTA LAND CRUISER	JTMHV09J604105334
75	GN 6323 - 13	TOYOTA LAND CRUISER	JTMHV09J4D4108278
76	GM 3705 - 13	TOYOTA LAND CRUISER	JTMHV09JXD4098789
77	GR 5863 - 11	TOYOTA PRADO	JTEBH9FJ2B5007992
78	WR 1732 - 16	TOYOTA LAND CRUISER V8	JTMHV09J6D4115233
79	GE 3008 - 13	TOYOTA LAND CRUISER V8	JTMHV09J6D4091421
80	UE 158 - 16	IVECO BUS	ZCFK050905076200
81	VR 4987 - 15	TOYOTA LAND CRUISER	JTMHV09J6A500431
82	NR 1273 - 15	TOYOTA LAND CRUISER	JTMHV09J3D4102424
83	AS 4212 - 09	TOYOTA LX	JTGEB73J9A9002455
84	ER 1504 - 15	TOYOTA LAND CRUISER	JTMHV09J7F4169927
85	GT 4187 - 09	TOYOTA HILUX PICK UP	MR0FR22G1A0552051
86	GE 2942 - 14	NISSAN NAVARA PICK UP	MNTCD0HY3D6600504
87	GV 15 - 16	IVECO BUS	ZCFK050A605076199
88	GV 20 - 16	IVECO BUS	ZCFK050A005076747
89	GE 6683	TOYOTA LX PICK UP	JTFLB71J2C8034994
90	BA 5605 - 15	TOYOTA LAND CRUISER	JTMHV09J905017835
91	ER 8250 - 15	TOYOTA LAND CRUISER	JTMHV09J6F5032530
92	ER 1545 - 15	TOYOTA LAND CRUISER	JTMHV09J1F5032905
93	UE 1154 - 13	TOYOTA LAND CRUISER	JTMHV09J9D4106526
94	GN 8460 - 13	TOYOTA LAND CRUISER	JTMHV09J0D4102963
95	UW 48 - 09	FORD EXPEDITION	IFMFK20518LA85139
96	AS 4216 - 09	MERCEDES BENZ	WDD2211711A026566
97	GR 2078 - 16	TOYOTA AVALON	
98	GC 4764 - 11	MERCEDES BENZ	WDD2211571A422020
99	GV 506 - 14	TOYOTA LAND CRUISER	JTMHV09J3D4104383
100	GS 683 - 13	TOYOTA LAND CRUISER	JTMHV09J7D4096465
101	GM 2041 - 16	TOYOTA LX	JTGE73J1C9009273
102	NR 1808 - 16	TOYOTA FORTURNER	MHFYX59G288013653
103	VR 6125 - 14	TOYOTA LAND CRUISER V6	JTMHU09J9E5080539
104	GE 2950 - 14	NISSAN PATROL	
105	GB 246 - 12	TOYOTA LX	JTGEB73J4A9002458
106	GV 120 -15	TOYOTA LX	JTFLB71J2C8033988
107	VR 1605 - 16	TOYOTA LX	JTFLB71J0C8035030
108	ER 4415 - 10	TOYOTA LX	JTCEB73J8A9002429
109	GE 2316 - 14	NISSAN NAVARA PICK UP	MNTCD0EY0D6600691
110	GV 94 - 15	TOYOTA LAND CRUISER	JTMHV09J095001469
111	NR 2048	TOYOTA LAND CRUISER	JTMHV09J4F4159069
112	NR 315 - 10	TOYOTA LAND CRUISER	JTMHV09J604047817
113	GR 638 - 10	TOYOTA LAND CRUISER	JTMHV09J404038968
114	GE 2983 -13	TOYOTA LAND CRUISER	JTNHV09JXD4091082
115	GV 113 - 15	MERCEDES BENZ AMBULANCE	WB9066331P116501
116	GE 3285 - 11	TOYOTA LAND CRUISER V6 AMBU	JTMDU09J8A5033110
117	GV 114 - 15	BENZ AMBULANCE	WDB9066331P123571
118	GR 3252 - 09	HYUNDAI COUNTY BUS	KMJHD17C1AC046377

OFFICER HANDING OVER: HARISSON KOFI AWUKU  
OFFICER TAKING OVER: CAPT SAMUEL ANANE-TANOR

119		HYUNDAICOUNTY BUS	KHJB7LXFC064438
120	ER 427 - 15	HYUNDAI COUNTY BUS	KHJHG17C9FC084432
121	ER 1529 - 15	TOYOTA LAND CRUISER	JTMHV09J3F5032873
122	GM 3708 - 13	TOYOTA LAND CRUISER	JTMHV09J9E412391
123	GW 8221 - 11	TOYOTA LAND CRUISER	JTMHV09J994034637
124	GE 2364 - 16	TOYOTA LAND CRUISER	JTMHV09J2E4122178
125	ER 4414 - 10	TOYOTA HILUX PICK UP	MR0FR22G2A0552737
126	GE 1107 - 13	FORD TRANSIT BUS	NM0DXXTTFDCK69315
127	BA 260 - 16	IVECO BUS	ZCFK050A605077255
128	NR 1107 - 16	IVECO BUS	ZCFK050A905076472
129		MERCEDES BENZ S500	WDD2211711A022986
130	GV 514 - 14	TOYOTA PRADO	TEBH9FJ1DK095843
131	GR 3230 - 09	BMW	WBAHN21060D593682
132	GW 8231 - 11	BMW	WBAHN21030D593316
133	GW 7297 - 16	NISSAN ARMADA	5N1AA0NC7DN608817
134	GE 4165 - 14	NISSAN PATROL V8	JN8AY2NY1E9070816
135	GE 4159 - 14	NISSAN PATROL V8	JN8AY2NY8E9071073
136	VR 1338 - 16	NISSAN PATROL V8	JN8AY2NY6E9071153
137	GW 8212 - 11	FORD EXPEDITION KING RANCH	1FMJU1J58AFB60748
138	VR 6561 - 16	TOYOTA LAND CRUISER	JTMHY05J1D4016736
139		TOYOTA LAND CRUISER	JTMHY05J4D4016990
140	BA 254 - 16	IVECO BUS	ZCFK050A205077253
141		TOYOTA LAND CRUISER V8	JTMHV09J2F4173584
142		TOYOTA LAND CRUISER V8	JTMHV09J9F4171492
143		TOYOTA LAND CRUISER V8	JTMHV09J5F4170646
144		TOYOTA LAND CRUISER V8	JTMHV09J8F4158250
145		TOYOTA LAND CRUISER V8	JTMHV09J3F4171617
146		TOYOTA LAND CRUISER V8	JTMHV09J8F4175209
147	GB 6409 - 12	TOYOTA FORTURNER	MHFYX59G3C8034097
148	VR 106 - 09	TOYOTA LAND CRUISER	JTECB09J703023045
149	GT 1712 - 14	TOYOTA LAND CRUISER PICK UP	MRDFR22G4D0688579
150	GE 2947 - 14	TOYOTA PRADO	JTEJ49U9FJSCF031776
151	GM 3446 - 16	TOYOTA LAND CRUISER V8	JTMHV09J3C4084974
152	BA 5409 - 15	TOYOTA LAND CRUISER	JTMHV09J8F4124338
153	ER 1556 - 15	HYUNDAI BUS	KMJHJG17C6FC064422
154	GR 1519 - 15	TOYOTA LAND CRUISER V8	JTMHV05J004122758
155	NR 1732 - 16	TOYOTA LAND CRUISER V8	JTMHV09J3F4171617
156	GR 2153 - 16	TOYOTA LAND CRUISER V8	JTMHV09J2F503320
157	NR 5184 - 15	TOYOTA LAND CRUISER V8	JTMHV05J3F4160455
158	VR 2105 - 15	TOYOTA LAND CRUISER V8	JTMHV05J204152697
159	GR 3874 - 09	MITSUBISHI RECOVERY	JL6BCE6J7BK009712
160	GC 6830 - 09	TOYOTA LX	JTGEB73J999001625
162	8905 - 09	TOYOTA LX	JTGEB73JXD9010441
163	GV 137 - 15	TOYOTA PRADO	JTEBH9FJ5F5089190
164	GE 2995 - 14	TOYOTA LAND CRUISER	JTMHV09J2E4122746
165	GV 5 - 14	TOYOTA LAND CRUISER	JTMHV09J804050542
166	GE 2616 - 14	TOYOTA CAMARY	6T1BF9FK0DX454024
167	VR 3654 - 15	TOYOTA PRADO	JTEBH9FJ5FK158462
168	CR 362 -15	TOYOTA AVENSIS	SB1BL76L70E039444
169	GR 4729 - 16	TOYOTA LAND CRUISER	JTMHV09JXF4160338
170		BMW	WBAHP61070DD19078
171		BMW	WBAHP61050DD19080
172	GW 8217 - 11	BMW	WBAHN21080DS93604
173	ER 2137 - 14	BMW	

OFFICER HANDING OVER: HARISSON KOFI AWUKU  
OFFICER TAKING OVER: CAPT SAMUEL ANANE-TANOR

**UNSERVICEABLE VEHICLES AT POINT SIX (KOSOVO)**

<b>SRL</b>	<b>VEH NO</b>	<b>MAKE OF VEH</b>	<b>CHASSIS NO</b>	<b>LOCATION</b>	<b>REMARKS</b>
<b>(a)</b>	<b>(b)</b>	<b>(c)</b>	<b>(d)</b>	<b>(e)</b>	<b>(f)</b>
1	GE 2928 - 14	TOYOTA LAND CRUISER V8	JTMHV09JBE4124467	POINT 6	
2		TOYOTA LAND CRUISER V8	JTMHV09J9A5005055	POINT 6	
3		TOYOTA LAND CRUISER	JTMHDV09J994035320	POINT 6	
4		TOYOTA LAND CRUISER	JTMHV09J7B4068744	POINT 6	
5	GN 4597 - 13	FORD BUS	1FB553DL3DDB33401	POINT 6	
6		TOYOTA LAND CRUISER V8	JTMHV09J8D4094871	POINT 6	
7	CR 147 W	TOYOTA HILUX PICK UP	JTFED42660008828	POINT 6	
8	ER 2259 - 09	NISSAN PATROL PICK UP	JN6BY15Y4AA509121	POINT 6	
9	GR 2661 - 12	TOYOTA LAND CRUISER PICK UP	MR0FR22G8C0667751	POINT 6	
10	GR 3236 - 09	MERCEDES BENZ 5350	WDD2210561A016016	POINT 6	
11	GT 2782 - 14	TOYOTA FORTURNER	MHFYX59G1E8051015	POINT 6	
12	AW 5459 - 13	TOYOTA LAND CRUISER	JTMHV09J0C4083460	POINT 6	
13	GN 6311 - 13	TOYOTA LAND CRUISER V8	JTMHV09J3C4081928	POINT 6	
14	ER 317 - 09	TOYOTA LAND CRUISER V8	JTMHV09J0A85005137	POINT 6	
15	GE 2933 - 14	TOYOTA LAND CRUISER V8	JTMHV09J4E4123977	POINT 6	
16	ER 4409 - 10	TOYOTA LAND CRUISER V8	JTMHV09J105020812	POINT 6	
17	GE 2935 - 14	TOYOTA LAND CRUISER V8	JTMHV09J4E4124062	POINT 6	
18	GN 2967 - 13	TOYOTA LAND CRUISER V8	JTMHV09J7C4073590	POINT 6	
19	ER 4408 - 10	TOYOTA LAND CRUISER V8	JTMHV09J905019584	POINT 6	
20	GS 7804 - 10	TOYOTA LAND CRUISER V8	JTMHV09J4A5008350	POINT 6	
21	GW 6345 - 09	TOYOTA LAND CRUISER V8	JTMHV09J594034540	POINT 6	
22	ER 4412 - 10	TOYOTA LAND CRUISER V8	JTMHV09J205015831	POINT 6	
23	GT 4174 - 09	TOYOTA LAND CRUISER V8	JTMHV09J384003382	POINT 6	
24		TOYOTA LAND CRUISER V8	JTMHV05J304155009	POINT 6	
25		TOYOTA LAND CRUISER V8	JTMHV09J4F4158195	POINT 6	

OFFICER HANDING OVER: HARISSON KOFI AWUKU

OFFICER TAKING OVER: CAPT SAMUEL ANANE-TANOR

26		TOYOTA LAND CRUISER V8	JTMHV09J805017860	POINT 6	
27		TOYOTA LAND CRUISER V8	JTMHV09J5C4074012	POINT 6	
28		TOYOTA LAND CRUISER V8	JTMHV09J4C4082778	POINT 6	
29		TOYOTA LAND CRUISER V8	JTMHV09J2A4047444	POINT 6	
30	GR 2289 - 16	TOYOTA LAND CRUISER V8	JTMHV09J1D4097692	POINT 6	
31		TOYOTA HILUX	AHTFK22G703018099	POINT 6	
32	UE 7609	TOYOTA LAND CRUISER LX	JTGEB73J649002431	POINT 6	
33		TOYOTA HAICE	JTFJK02P300002941	POINT 6	
34	GV 253 - 12	VW	WV1ZZZ7HZCH090532	POINT 6	
35	GT 27779 - 14	TOYOTA HAICE	JTGJ50ZP3B0038159	POINT 6	
36	UW 3194	FORD EXPEDITION	1FMFU16578LA08822	POINT 6	
37		FORD EXPEDITION	1FMJU1J52B6F40198	POINT 6	
38	GR 3248 - 09	NISSAN PAJERO	JMYLYF98W8J733736	POINT 6	
39	GT 4184 - 09	EICHER		POINT 6	WATER TANKER
40		NISSAN SONY SALOON	NDHBN1AD7D6029125	POINT 6	
41	GT 4182 - 09	NISSAN PAJERO	JMYLYV98W8J734445	POINT 6	
42		HONDA MOTOR BIKE		POINT 6	
43		HONDA MOTOR BIKE		POINT 6	
44	GN 2967 - 13	TOYOTA LAND CRUISER V8	JTMHV09J7C4073590	POINT 6	
45		NISSAN PICK UP	JN6BY152AA509120	POINT 6	

OFFICER HANDING OVER: HARISSON KOFI AWUKU

OFFICER TAKING OVER: CAPT SAMUEL ANANE-TANOR